


# SUBMITTAL DATA SHEET

Pump Repair Parts

## 8300 Series Repair Parts




## 8000 Series Jet Pumps Repair Parts



Model No.	Imp/Dif Kit	Seal Kit	Venturi Kit	Casing	Model No.	Imp/Dif Kit	Seal Kit	Venturi Kit	Casing
8350	6156-129	6156-133	6156-147	6156-145	8310	6156-131	6156-141	6156-149	6156-145
8350HP	6156-129	6156-133	6156-151	6156-145	8315	6156-132	6156-141	6156-150	6156-145
8370	6156-130	6156-133	6156-148	6156-145					

\*Imp/Dif Kit includes - impeller, diffuser, rotary seal, housing o-ring, seal ring, and diffuser screws  
 \*Seal Kit includes - rotary seal, housing o-ring and seal ring

## 8300 Series Jet Pumps Repair Parts



Model No.	Imp/Dif Kit	Seal Kit	Venturi Kit	Casing	Model No.	Imp/Dif Kit	Seal Kit	Venturi Kit	Casing
8350	6156-129	6156-133	6156-147	6156-145	8310	6156-131	6156-141	6156-149	6156-145
8350HP	6156-129	6156-133	6156-151	6156-145	8315	6156-132	6156-141	6156-150	6156-145
8370	6156-130	6156-133	6156-148	6156-145					

\*Imp/Dif Kit includes - impeller, diffuser, rotary seal, housing o-ring, seal ring, and diffuser screws  
 \*Seal Kit includes - rotary seal, housing o-ring and seal ring

NO-LEAD: The weighted average of the wetted surface of this no-lead product contacted by consumable water contains less than one quarter of one percent (0.25%) lead.



**A.Y. McDonald Mfg. Co.**  
 4800 Chavenelle Rd  
 Dubuque, IA 52002

**Toll Free: 1-800-292-2737**  
 sales@aymcdonald.com  
 aymcdonald.com

A.Y. McDonald considers the information on this assembly drawing correct when published. Item and option availability, including specifications, are subject to change without notice.

Submitted by: